Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/10001BL0425/1
Work Order Type: Weatherization
Audit Name: 10001BL0425

CLIENT INFORMATION

Client Name: Address:

Client ID: 10001BL0425 , 37803

Alt. Client ID: BLOUNT

<u>AGENCY INFORMATION</u>

Agency: Blount County Community Action Agency

Agency Phone: (865) 983-8411

Address: 3509 Tuckalee Pike **Fax:** (865) 681-1781

Maryville, TN 37803 *Email Address:*

Agency Contact: Larson, Bruce Work Phone:

Cell Phone: (865) 310-7333

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Auditor: Bruce Larson (865-310-7333)

Audit conducted on 1/14/2012

Site Built: Pre 1910

Practice Lead Safe Weatherization Installation of Wall insulation in stair way

(Remove/Replace broken window panes in several windows.)

Client Name:
Client ID: 10001BL0425
Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0425/1 Report Run On: 1/30/2012 DOE Weatherization Assistant Version 8.6.0

Page 1 of 10

,		ame for and Install Prehu ore Door at top of Attic St	•	w	Componen	ts		1	Inspected
C	•	loss of air at top of attic state to late to l	•				install		
	Left o	actor will need to frame for r right hand. (contractor's o with NO LOCK. Interior Ho	choice) Sh	eet ro	ck finish. No	paint. tA aming)		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					
c	Other Detail								
			ı	Measur	e Sub Total:] ,	Sub Total:	
	cra crament crawls 1/4" p	ame in existing opening awlspace door and instal awlspace door. e in existing opening to craspace door . 2x4 for framinally wood for door. Paint whilest standing up against open	II new wlspace (2 ng. te,add hard		•	all new	s rotted		Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					
IU									
	Other Detail								
	Other Detail								
	Other Detail								
	Other Detail			Measur	e Sub Total:			Sub Total:	

Client Name:
Client ID: 10001BL0425
Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0425/1 Report Run On: 1/30/2012 Version 8.6.0 Page 2 of 10

Measu		all approx. (320) sq. ft R lulose in Interior Walls	R -11 Blow	/n	Componen	ts			Inspected
Comme		approx. (320) sq. ft. of blo y to attic. Large loss of ai			interior wall	going up			
					Estimated			Actual	
# Materi	ial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Unspe	ecified	Misc Material	Each	1					
Other De	e <i>tail</i>								
				Measur	e Sub Total:		,	Sub Total:	
Field N	lotes:								
Measu		all Vinyl Double Pane/D		ng	Componen	ts			Inspected
	Rep ent Remove	lacement Window(28" e /Replace Window # 10 v	x 54") with Doub	le Pan	- e/Double Hu	ng Repla		t	Inspected
	Rep ent Remove	lacement Window (28"	x 54") with Doub	le Pan	- e/Double Hu	ng Repla Size: 28		t	Inspected
Comme	Rep ent Remov	lacement Window(28" e /Replace Window # 10 v	x 54") with Doub	le Pan	e/Double Hu ow is rotted.	ng Repla Size: 28		t)	Inspected
Comme	Repent Remove Windov	placement Window (28" e /Replace Window # 10 v	x 54") with Doub en out, and	le Pand d windd	e/Double Hu ow is rotted. <i>Estimated</i>	ng Repla Size: 28	" x 54"	t) Actual	
Comme	Repent Remove Window ial / Labor ecified	e /Replace Window (28" e /Replace Window # 10 v v. All the panes are broke Description / Comment	x 54") with Doub en out, and <i>Unit</i> s	le Pand d windd Qty	e/Double Hu ow is rotted. <i>Estimated</i>	ng Repla Size: 28	" x 54"	t) Actual	
# Materi	Repent Remove Window ial / Labor ecified	e /Replace Window (28" e /Replace Window # 10 v v. All the panes are broke Description / Comment	x 54") with Doub en out, and <i>Unit</i> s	le Pand d windd Qty	e/Double Hu ow is rotted. <i>Estimated</i>	ng Repla Size: 28	" x 54"	t) Actual	
Comme # Materi 0 Unspe	Repent Remove Window ial / Labor ecified	e /Replace Window (28" e /Replace Window # 10 v v. All the panes are broke Description / Comment	x 54") with Doub en out, and <i>Unit</i> s	le Pand d windd Qty	e/Double Hu ow is rotted. <i>Estimated</i>	ng Repla Size: 28	" x 54"	t) Actual	
Comme # Materi 0 Unspe	Repent Remove Window ial / Labor ecified	e /Replace Window (28" e /Replace Window # 10 v v. All the panes are broke Description / Comment	x 54") with Doub en out, and Units Each	le Paned windo	e/Double Hu ow is rotted. <i>Estimated</i>	ng Repla Size: 28	" x 54"	t) Actual	
# Materi 0 Unspe	Repent Remove Window Window etail	e /Replace Window (28" e /Replace Window # 10 v v. All the panes are broke Description / Comment	x 54") with Doub en out, and Units Each	le Paned windo	e/Double Hu ow is rotted. Estimated Unit Cost	ng Repla Size: 28	" x 54"	t) Actual Unit Cost	
Comme # Materi 0 Unspe	Repent Remove Window Window etail	e /Replace Window (28" e /Replace Window # 10 v v. All the panes are broke Description / Comment	x 54") with Doub en out, and Units Each	le Paned windo	e/Double Hu ow is rotted. Estimated Unit Cost	ng Repla Size: 28	" x 54"	t) Actual Unit Cost	

 Work Order Name: WO/10001BL0425/1
 Version 8.6.0

 Report Run On: 1/30/2012
 Page 3 of 10

# 10	nove/Replace framing fr 0. (28" x 54")			Componen			I	nspecte
old fran	ming is rotted in Window ning with new framing. Wi w framing needed.				•			
				Estimated	1		Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Unspecified	Misc Material	Each	1					
Other Detail						,		
] [
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Mossuro	6	Infiltration	Padeta
weasure	0	IIIIIIIIII alioii	Reucin

Components

Inspected

Comment

- 1. Seal/foam around water/drain lines in kitchen sink
- 2. Weather strip DR 2 (32" x 78")
- 3. Weather Strip DR 3 (32" x 78 ")
- 4. Install threshhold to DR 3 (32" x 78")
- 5. Foam (3" x 6") opening under bathroom sink
- 6. Remove/Replace (2) broken window panes in # 3 Window (Each pane is (7" x 24") Reglaze. (Lead paint)
- 7. Remove/Replace (2) broken panes in Window # 14. (7" x 24") each pane. (Lead paint) Reglaze.
- 8. Remove/Replace Bottom pane in Window # 14. (23" x 23") Reglaze Lead Paint
- 9. Remove/Replace broken pane in Window # 15. (23" x 23") Reglaze Lead paint.
- Remove/Replace broken bottom pane in Window # 16. (23" x 23")
 Reglaze. Lead Paint
- 11. Caulk (white) all exterior window frames/brick, on (16) windows. (2 windows measure 28" x 39") and 14 windows measure (28" x 54"). Approx. 36 linear feet of caulk.
- 12. Weather Strip Interior door in attic. Goes from Finished to unfinished part of attic.

				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscellaneous Su	Infiltration Reduction	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Client Name:
Client ID: 10001BL0425
Alt. Client ID: BLOUNT

Work Order (Bid Form)
Work Order Name: WO/10001BL0425/1

Report Run On: 1/30/2012

DOE Weatherization Assistant Version 8.6.0

Page 5 of 10

Dirt Flo	oor/Sump Pump							
				Estimated	•		Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Tota
Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	600					
Labor	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	600					
ther Detail] [
] []		
Field Notes:			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	
Measure 8 DW	/H Pipe Insulation e 6' water pipes each (Ho		Measur	Componen				Inspec
Measure 8 DW omment Insulat	e 6' water pipes each (Ho							Inspec
Measure 8 DW omment Insulat Material / Labor	-	t/Cold)	Measur Qty 1	Componen Estimated		Qty	Actual	
Measure 8 DW omment Insulat Material / Labor Insulation	e 6' water pipes each (Ho Description / Comment	t/Cold) <i>Unit</i> s	Qty	Componen Estimated			Actual	
Measure 8 DW	e 6' water pipes each (Ho Description / Comment DHW Pipe Insulation	t/Cold) <i>Units</i> Each	Qty 1	Componen Estimated			Actual	
Measure 8 DW omment Insulat Material / Labor Insulation Labor	e 6' water pipes each (Ho Description / Comment DHW Pipe Insulation	t/Cold) <i>Units</i> Each	Qty 1	Componen Estimated			Actual	

	Measure 9 DWH	H Tank Insulation			Componen	its			Inspected
C	comment 40 gallo	n Electric							
					Estimated	ı		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equip	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
(Other Detail						1		
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								

/	<i>Measure</i>	10 Stor	m Windows			Componen	3,EW 4,EW 14,SV 16,NV 5,EW 11,WV		D SWD WD VD WWD	Inspected
C	omment	NOTE: S Storm W	Some windows will need /indows.	broken pa	anes re	placed prior	•	•		
		Total of	15 Windows.							
			dows measure (28" x 39 ndows measure (28" x 5							
#	Material /	Lahor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
	Windows		Storm Window	SqFt	148.8		Total			- Total
2	Labor		Storm Window	SqFt	148.8					
3	Other		Storm Window	Each Window	15					
C	Other Detai	1						_		
					Measur	e Sub Total:] ;	Sub Total:	
	Field Note	es:								

ı	<i>Measur</i> e 11 Atti	ic Ins. R-30			Componen	ts AT 1			Inspected
C	omment Existing	g R value of 9							
	Bring to	o R-38							
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Cellulose, Blown - R-30	SqFt	800					
2	Labor	Attic Insulation - Cellulose, Blown - R-30	SqFt	800					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	omment Install (Monitor is Needed CO Monitor has Oil heat			Componen			Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0	Unspecified	CO monitor (+)	Each	1					
_	Other Detail								
Ĭ	ther Detail								
Ī									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:				L				

	<i>Measur</i> e 13 Pra (Wa	ctice Lead Safe Weather alls)	rization		Componen	ts		1	Inspected
C	omment Site Bu	•							
		e Lead Safe Weatherization ation of Wall Insulation)	on						
	(Remov	ve/Replace broken windov	v panes ir	n sever	al windows.) <i>Estimated</i>			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0	Unspecified	Misc Material	Each	1					
C	Other Detail	7					1		
L] []		
				Measur	e Sub Total:			Sub Total:	
L									
		ssureRelief Piping Need 36") Pressure Relief Pipi			Componen				Inspected
C	omment Install (36") Pressure Relief Pipi		Qtv	Estimated		Qty	Actual	Inspected Total
<i>C</i> #		. •	ing	Qty 1	•		Qty		
C # 0	omment Install (Material / Labor Unspecified	36") Pressure Relief Pipi Description / Comment	ing <i>Unit</i> s		Estimated		Qty	Actual	
C # 0	omment Install (36") Pressure Relief Pipi Description / Comment	ing <i>Unit</i> s		Estimated		Qty	Actual	
C # 0	omment Install (Material / Labor Unspecified	36") Pressure Relief Pipi Description / Comment	ing <i>Unit</i> s		Estimated		Qty	Actual	
C # 0	omment Install (Material / Labor Unspecified	36") Pressure Relief Pipi Description / Comment	ing <i>Unit</i> s	1	Estimated			Actual	
C # 0 C	omment Install (Material / Labor Unspecified	36") Pressure Relief Pipi Description / Comment	ing <i>Unit</i> s	1	Estimated Unit Cost			Actual Unit Cost	
C # 0 C	omment Install (Material / Labor Unspecified Other Detail	36") Pressure Relief Pipi Description / Comment	ing <i>Unit</i> s	1	Estimated Unit Cost			Actual Unit Cost	
C # 0	omment Install (Material / Labor Unspecified Other Detail	36") Pressure Relief Pipi Description / Comment	ing <i>Unit</i> s	1	Estimated Unit Cost			Actual Unit Cost	
C # 0	omment Install (Material / Labor Unspecified Other Detail	36") Pressure Relief Pipi Description / Comment	ing <i>Unit</i> s	1	Estimated Unit Cost			Actual Unit Cost	